

Job #5112589200

(Plumbing Service) Plumbing Checklist

Customer Information

Customer

Saeed Ata

Address of job

6014 Parsons Pond Drive, Ooltewah, TN 37363 USA

Reason Customer Called

-

Job Number

5112589200

Technician Information

Tech

Steven Walker

Date

2024-10-18

Are you primary on the job

yes

Call Information

Type of Call

Leak

Before pictures of work area

Picture of work area before work starts



Are you able to complete the checklist for this job?

yes

General Information

Static Water Pressure

Must be checked on every call

65

Hot Water Temp

Max temp 120 Degs

120

Water Quality

Hardness and Chlorine Levels

Select all that apply

Chlorine high

Foundation Type

Basement

Type of Leak

Type of leak

In Home Water

Fixture Leaking

Main vslve

Piping Leaking

Copper

Leak visable

Yes

Covered Drywall Repairs

Hiller does not repair drywall

For an additional charge we can install an access panel.

No

Issues discovered and solutions given

Yes

Job Close Out Report

Customer Down

Unable to use any item in their home

No

Project Manager in Route

No

Holding for Parts

No

System tested and working correctly

Yes

Material Usage Recorded

Yes

Jobsite cleaner than before

Yes

Customer Joined HHC

No

Payment

CC

Signatures

Are you Happy with services provided today?



**Tech
Signature**

